


Slim SMA, SlimSMAW FRED Pt®



Note:
 • Cathode band: marked with one or more lines

1st row

1 H 2

1 — Volt class
 1 = 100..
 2 = 200..
 3 = 300..
 ...

H — Process type
 X = Hyperfast recovery time
 H = Hyperfast recovery time
 U = Ultrafast recovery time
 L = Low Vf Ultrafast recovery time

2 — Current
 1 = 1A
 2 = 1A
 3 = 3A ..

2nd row

X Y

Y — Month
 1 to 9 = Jan to Sep
 A = Oct
 B = Nov
 C = Dec

X — Year
 1 = 2011
 2 = 2012 ..

3rd row

Z

Z — Environmental digit

ENVIRONMENTAL NAMING CODE	PRODUCT DEFINITION
A	Termination lead (Pb)-free
B	Totally lead (Pb)-free
E	RoHS-compliant + termination lead (Pb)-free
F	RoHS-compliant + totally lead (Pb)-free
M	Halogen-free + RoHS-compliant + termination lead (Pb)-free
N	Halogen-free + RoHS-compliant + totally lead (Pb)-free
G	Green